5

10

Abstract

A method of mass-producing a solid state device comprises providing an atomically smooth, solid state material layer no 15more than 40 Angstroms thick. This layer is uniformly and defect-freely bonded onto a substrate to provide an acceptable device yield.